## **Under Review Notification**

Raised By: Vanessa Morel Product #: 269A9232

Date: 2019.11.08 Product Name: BEARING REMOVAL PLUG

		"Y" or "N" Required for Each Part							:		
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
269A9232	269A9232 Rev	Υ	Υ	Ν	Υ	Υ	N	Ν	N	19-1264	See below

## Description of Issue:

Issues stated on ADR (Napkin drawing)

269A9232 must be put on HOLD in Plex

269A9232 Finish good stock must be put in quarantine

All subs and parts in stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of OperationsChief EngineerProduction EngineersProduct Manager - Solutions ProviderDirector Quality AssuranceEngineering Project ManagersProduction PlannersSupply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene